



**Beaufort County
Public Works
Stormwater Infrastructure
Project Summary**

Project Summary: Clarendon Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Assisted SCDOT with crossline repair.

Duration: 4/7/16 - 7/21/16

2017-004 / Clarendon Road

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CLJS / Cleaned up jobsite	10.0	\$240.89	\$128.60	\$71.35	\$0.00	\$138.25	\$579.09
HAUL / Hauling	5.0	\$111.35	\$47.10	\$21.42	\$0.00	\$72.10	\$251.97
ONJV / Onsite Job Visit	5.0	\$130.76	\$25.20	\$6.96	\$0.00	\$81.99	\$244.91
SPSWI / Special Project - SWI	45.0	\$1,132.29	\$262.97	\$32.23	\$0.00	\$691.70	\$2,119.18
UC / Utility Coordination	1.5	\$37.05	\$5.40	\$3.48	\$0.00	\$19.85	\$65.78
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2017-004 / Clarendon Road Sub Total	67.5	\$1,676.44	\$469.27	\$135.44	\$0.00	\$1,017.11	\$3,298.26
 Grand Total	 67.5	 \$1,676.44	 \$469.27	 \$135.44	 \$0.00	 \$1,017.11	 \$3,298.26

Before



During



After





Project: Clarendon Road

Activity: Routine/ Preventive Maintenance

Project #: 2017-004

Township/SW Dist: Port Royal Island/6

Completed: September 2016

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 100 feet