



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Port Royal Island Bush Hog

Activity: Routine/Preventive Maintenance

Duration: 11/20/17-04/05/18

Narrative Description of Project:

Second Rotation: 11/20/17-04/05/18: Project improved 24,286 L.F. of drainage system. Bush hogged 24,286 L.F. of channel. This project consisted of the following areas: Young Circle (330 L.F.), Gillison Loop (520 L.F.), Chisolm Hill Road (3,850 L.F.), Gamecock Way (2,630 L.F.), Paukie Island Road (1,000 L.F.), Smalls Hill Road (1,255 L.F.), Mulrain Road (540 L.F.), Smith Road (330 L.F.), Salem Drive East (1,200 L.F.), Ihly Farm Road (4,090 L.F.) Quail Drive (335 L.F.), Shanklin Road (8,206 L.F.)

2018-301A / Port Royal Island Bush Hog

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CBH / Channel- bushhogged	232.0	\$4,823.29	\$2,473.90	\$648.12	\$0.00	\$2,378.88	\$10,324.19
2018-301A / Port Royal Island Bush Hog Sub Total	232.5	\$4,834.19	\$2,473.90	\$648.12	\$0.00	\$2,378.88	\$10,335.09
Grand Total	232.5	\$4,834.19	\$2,473.90	\$648.12	\$0.00	\$2,378.88	\$10,335.09